

Legend:

T	Total support. An instrument can be repaired and calibrated
P	Partial support. Depending on the issue, we may not be able to repair the instrument. For instance, if there's a shortage of components due to their age and unavailability on the market. In such cases, certification cannot proceed either.
E	End of the support. Please do not send the instrument to our laboratories, as it will be returned to the sender.

Model	Description	Manufacturing Status	Repair Service
1001	Impedance Network	Discontinued since January 2008	E
1003	3-phase Impedance Network	Discontinued since January 2008	E
3000	Signal generator	Discontinued. Replaced by 3010/3030	E
6000	Linear amplifier RF	Discontinued since January 2010. Replaced by 6000N	E
6000N	Linear amplifier RF	Discontinued since April 2017. Replaced by PA6002	P
6600 + 6485	RF Power meter for EMC application	Discontinued. Replaced by 6630	E
7000	EMI Receiver	Discontinued since March 2013	E
7010/00	EMI CISPR Receiver Pre compliance	Discontinued since January 2021. Replaced by ER8000/00-ER8000/01	P
7010/01	EMI CISPR Receiver Pre compliance	Discontinued since October 2023. Replaced by ER8000/00-ER8000/01	T
7010/02	EMI CISPR Receiver Pre compliance	Discontinued since October 2023. Replaced by ER8000/00-ER8000/01	T
7010/03	EMI CISPR Receiver Pre compliance	Discontinued since October 2023. Replaced by ER8000/00-ER8000/01	T
8000	EMI CISPR Receiver Pre compliance	Discontinued	E
8000 plus	EMI Receiver	Discontinued	E
8010 Win	Emi Receiver	Discontinued	E
8030 Win	Emi Receiver	Discontinued	E
8051	Field Metering unit.	Discontinued	E
8052	Field Metering unit.	Discontinued	E
8053	Field Metering unit.	Discontinued	E
8053A	Field Metering unit.	Discontinued since October 2004. Replaced by 8053B	E
8053 GPS	Option GPS	Discontinued	E
8055 (Every version 2 cells, 4 cells, IND)	Broadband Area Monitor	Discontinued since October 2016. Replaced by AMB-8059	E
8055 FUB	Broadband Area Monitor	Discontinued since December 2003	E
8056	RF Safety Analyzer	Discontinued since January 201	E
8057 (AMB and FUB)	Broadband Area Monitor	Discontinued since January 2016. Replaced by AMB-8059	E

Model	Description	Manufacturing Status	Repair Service
9000	EMI Receiver	Discontinued since March 2005. Replaced by 9010	E
9000/click	Click option for PMM 9000	Discontinued since March 2005	E
9000/GPIB	GPIB option for PMM 9000	Discontinued since March 2005	E
9010	EMI CISPR RECEIVER	Discontinued since January 2021. Replaced by 9010F	P
9010 Click 4E	Four Channels Click Meter Option	Discontinued since May 2018. Replaced by CA-0010	P
AD-7000	Active antenna for PMM 7000	Discontinued	E
AMS-8060	Selective area monitor	Discontinued since June 2015. Replaced by AMS-8061	E
BA-01	Isotropic E-Field Sensor	Discontinued	E
BA-02	Isotropic E-Field Sensor	Discontinued	E
BA-03	Isotropic E-Field Sensor	Discontinued	E
BA-04	Isotropic E-Field Sensor	Discontinued	E
BA-05	Isotropic E-Field Sensor	Discontinued	E
BA-06	Isotropic E-Field Sensor	Discontinued	E
BA-07	Isotropic E-Field Sensor	Discontinued	E
BA-08	Isotropic E-Field Sensor	Discontinued	E
EHP-200	Isotropic E&H-Field Analyzer	Discontinued since January 2011. Replaced by EHP-200A	E
EHP-50	Isotropic E&H-Field Analyzer	Discontinued	P
EHP-50A	Isotropic E&H-Field Analyzer	Discontinued	P
EHP-50B	Isotropic E&H-Field Analyzer	Discontinued Replaced by EHP-50C	P
EHP-50C	Isotropic E&H-Field Analyzer	Discontinued since January 2015.	T
EHP-50D	Isotropic E&H-Field Analyzer	Discontinued since January 2015. Replaced by EHP-50F	T
EHP-50E	Isotropic E&H-Field Analyzer	Discontinued since July 2015. Replaced by EHP-50G	T
EP-115	Isotropic E-Field Sensor	Discontinued	E
EP-3DB	Isotropic DUAL E-Field Sensor	Discontinued	E
EP-3DB FUB	Isotropic DUAL E-Field Sensor	Discontinued	E
EP-3TB	Isotropic TRI E-Field Sensor	Discontinued	E
EP-33A	Isotropic E-Field Sensor	Discontinued since August 2024	T
EP-33B	Isotropic E-Field Sensor	Discontinued since August 2024	T
EP-33C	Isotropic E-Field Sensor	Discontinued since August 2024	T
EP-33M	Isotropic E-Field Sensor	Discontinued since August 2024	T
EP-44M	Isotropic E-Field Sensor	Discontinued since August 2024	T
EP-645	Electric Field Probe	Discontinued since February 2011	T

L1-150	Single Line LISN	Discontinued Replaced by L1-150M	P
L2-10	Two Line Single Phase LISN	Discontinued	E
L2-16	Two Line Single Phase LISN	Discontinued since January 2001	E
L2-16A	Two Line Single Phase LISN	Discontinued since June 2006. Replaced by L2-16B	E
L2-25	Two Line Single Phase LISN	Discontinued	E
L2-D	Delta LISN	Discontinued since January 2018	E
L3-25	Three Line Single Phase LISN	Discontinued	E
LP-01	Log Periodic Antenna	Discontinued	P
OR-01	Optical repeater.	Discontinued since January 2000	E
OR-02	Optical repeater.	Discontinued Replaced by OR-03	E
PA-01	Preamplifier for PMM 8030	Discontinued	E
SB-04	Automatic switching box	Discontinued since February 2016	P
Station 2600 (every version)	Broadband Area Monitor	Discontinued since October 2016. Replaced by AMB-8059	E